

FINAAL VSOP LOCK OUT CNC



Date: 1/20/2016

Version: 1

Operation: LOCK OUT CNC

Parts:

Tools: CNC Lockout Keys

Safety: Wear Safety Glasses, steel toe boots

Approved by: **MONika Soos**



| Important Steps  | Key Points  |
|------------------|---|
| Turn Off Machine | Make sure all moving parts have come to a complete stop |

| Important Steps | Key Points |
|-----------------|------------|
| Turn Key        | Turn key   |

| Important Steps | Key Points                        |
|-----------------|-----------------------------------|
| Remove Key      | Remove key and keep upon yourself |


Date:

Version: 1


Operation:

Parts:

Tools:



hinge drill lock out.docx  
Yesterday at 10:32 AM



Presentation1.pptx  
Jun 12, 2017



Survey1.xlsx  
Feb 28



V-SOP Master4-Sofo.xlsx  
Yesterday at 10:38 AM